

SB, CRT Kubota engines exhaust system correct torque values, CRT 48-33K, CRT 48-57K, 2024-01

SYMPTOM/DESCRIPTION

Due to incorrect torque values on the exhaust system, a leakage could occur which causes the engine to fall out of emission specification.

AFFECTED UNITS

All Kubota equipped CRT machines up to:

SN 1407488003 for CRT 48-33K

SN 1407827003 for CRT 48-57K

SKU	Model
970461603	CRT 48 57K Ride-On Trowel
970461607	CRT 48 33K Ride-On Trowel
970461608	CRT 48 33K DF Ride-On Trowel
970461610	CRT 48 33K Ride-On Trowel EU
970461611	CRT 48 57K-PS Ride-On Trowel
970461612	CRT 48 33K DF Ride-On Trowel EU
970461613	CRT 48 57K-PS Ride-On Trowel EU

CORRECTIVE ACTION

Check and if needed, correct the torques according to below instructions.




Fig. 1: Torque values for 33K models equipped with WG 972 engine.




Fig. 2: Torque values for 57K models equipped with WG 1605 engine.

WARRANTY INFORMATION

The normal warranty policy applies.

Revision History

Rev.	Date	Order id.	Description
A	2024-01	00038746	Created