

SB, Incorrectly installed indicator light decals, CRT 48-57K, CRT 48-57K PS, 2023-01

SYMPTOM/DESCRIPTION

The indicator light decals may have been applied incorrectly on some CRT 48 57K machines, produced between 1st of December 2022 and 1st of January 2023. This could lead to the operator having incorrect reading from the indicator lights.

AFFECTED UNITS

970461603 CRT 48-57K

SN affected:

1400112001, 1400378001, 1400436002, 1400437001, 1400437002, 1400464001, 1400464002, 1400596001, 1400741001, 1400742001, 1400743001, 1400744001, 1400806001, 1400807001, 1400807002, 1400807003, 1400870001, 1400871001, 1400871002, 1400899001, 1400900001, 1400900002, 1400901001, 1400901002, 1400902001

970461611 CRT 48-57K PS

SN affected:

1400314001, 1400315001, 1400315002, 1400316001, 1400377001, 1400436001

CORRECTIVE ACTION

- Inspect the control panel for correct placement of the indicator light decals as shown in the picture.
- Update the machines in the local stock.
- Call the customers to inspect the machines in the field.

PROCEDURE

Gently remove an incorrectly applied decal and replace it with the correct indicator decal as shown in picture.

PARTS INFORMATION

Replacement decal PN 599043101 to be ordered - 1 pcs per unit.

WARRANTY INFORMATION

The normal warranty policy applies.



Revision History

Rev.	Date	Order id.	Description
A	2023-01	00026804	Created