

SB, HMI fog, FS 5000, FS 7000 D, FS 7000 DL, FS 7000 DMT, 2018-08

SYMPTOM/DESCRIPTION

To prevent fog building up on the HMI screens there is a new solution with dryer bags inside the cover.



Figure 1

AFFECTED UNITS

FS 5000, FS 7000 D, FS 7000 DL, FS 7000 DMT.

Serial Number breaks:

FS 7000	1373768001
FS 5000	1373654001

CORRECTIVE ACTION

When fog occur on the screen the dryer bags needs to be replaced.
If you have an old HMI you need to replace it with a new HMI panel.

PROCEDURE

1. Remove cover on HMI back side, 4 nuts (fig 2).




Figure 2

2. Replace dryer bags (fig 3).



Figure 3

3. Replace cover gasket and 4 nuts (included in kit).
4. Put the cover in place and tighten the nuts.

PARTS INFORMATION

Description	Old article number	New article number
HMI FS 7000	589392001	593272501
HMI FS 5000	590046401	593272601
Dryer bag kit		595516801

WARRANTY INFORMATION

The normal warranty policy applies.