

SB, Wand, S 13, W 70, 2019-11

SYMPTOM/DESCRIPTION

The wand 590428601 for S 13 can fall apart.

A short term solution is in place since W38. All spare parts leaving supplier and the central warehouse in Sweden has been reworked.

A long term solution is under investigation, a notification will be sent out when it is in place.

AFFECTED UNITS

S 13

W 70

W 70 P

WARRANTY INFORMATION

The normal warranty policy applies.

Revision History

Rev.	Date	Order id.	Description
A	2019-11	SB-5041	Created