

SB, New EMI-Filter, D 20, D 30, W 70, W 70P, W 250P, S 13, S 26, S 36, 2024-06

SYMPTOM/DESCRIPTION

New EMI filter replaces old one.

Old number: 590427201

New number: **548068901**


AFFECTED UNITS

Model	Variants
D 20	EU, AU, UK
D 30	EU, AU
W 70	EU, AU, UK
W 70 P	EU, AU, UK, BR
W 250 P	EU, AU
S13	UK, BR
S 26	EU, AU, UK, BR
S 36	EU, AU, UK, BR, KSA

S/N's affected: All machines from ..20242170039.

CORRECTIVE ACTION

The pinout of the new EMI filter is different from the old one. Pay attention to which filter you are installing.





New filter



Old filter

Refer to complete electric schematics in the updated workshop manuals.

PARTS INFORMATION

Old stock will be used up before the new filter starts to sell.

WARRANTY INFORMATION

The normal warranty policy applies.

Revision History

Rev.	Date	Order id.	Description
A	2024-06	00058055	Created